

Great Park Operations and Maintenance Facility - WAG 061226



Excess dirt export underway



N & M geotechnical inspector verifying compaction



Over ex and compaction work ongoing for main building pad



Aerial view of progress at job site

